

Ackerman, Joyce

From:

Thomas J. Krasovec <TJKrasovec@Geosyntec.com>

Sent:

Wednesday, January 31, 2018 8:56 AM

To:

Ackerman, Joyce

Cc: Subject: Jonathan H. Steeler Photo Log of Labels

Attachments:

PhotoLog - current through 1-29-18.pdf

Joyce,

Attached is a brief photo log of the labeled drums and other items noted so far in the excavations. Please let me know if you have any questions. Drum numbers and-DFRs are noted on the pictures for further reference.

Thanks TJK

Thomas J Krasovec
Senior Professional
Geosyntec Consultants

Ph: 720-509-8911 Cell: 517-719-4984

Geosyntec Consultants, Inc.

5670 Greenwood Plaza Blvd, Suite 540

Greenwood Village, CO 80111

This message and any attachments may contain confidential information protected by attorney-client or other privilege. If you believe this message has been sent to you in error, please reply to the sender that you received it in error and delete the message. Thank you

Client: Stratus Redtail Ranch

LLC

Project Number: DE0302

Site Name: Stratus Redtail Ranch Site Location: Erie, CO

Photograph ID: 1

Date: 12/16/2017

Direction: N/A

Comments: Label on Drum from Phase 2B - RTR-68 (DFR-09)



Photograph ID: 2

Date: 12/16/2017

Direction: N/A

Comments: Same as above -

RTR-68



Client: Stratus Redtail Ranch

LLC

Project Number: DE0302

Site Name: Stratus Redtail Ranch Site Location: Erie, CO

Photograph ID: 3

Date: 12/14/2017

Direction: N/A

Comments: Label on Drum from

Phase 2A RTR-33 (DFR-07)



Photograph ID: 4

Date: 12/14/2017

Direction: N/A

Comments: Same as above.



Client: Stratus Redtail Ranch

LLC

Project Number: DE0302

Site Name: Stratus Redtail Ranch Site Location: Erie, CO

Photograph ID: 5

Date: 12/14/2017

Direction: N/A

Comments: Same as above



Photograph ID: 6

Date: 12/14/2017

Direction: N/A

Comments: Same as above



Client: Stratus Redtail Ranch

LLC

Project Number: DE0302

Site Name: Stratus Redtail Ranch Site Location: Erie, CO

Photograph ID: 7

Date: 12/16/2017

Direction: N/A

Comments: Lettering on drum from Phase 2B - RTR-75 (DFR-



Photograph ID: 8

Date: 12/17/2017

Direction: N/A

Comments: Label on Drum from Phase 2B - RTR-90 (DFR-10)



GEOSYNTEC CONSULTANTS Photographic Record Client: Stratus Redtail Ranch Project Number: DE0302

Site Name: Stratus Redtail Ranch Site Location: Erie, CO

Photograph ID: 9

LLC

Date: 12/17/2017

Direction: N/A

Comments: Same as above -RTR-90 - other part of label



Photograph ID: 10

Date: 12/18/2017

Direction: N/A

Comments: Explosive wire found

in Phase 2B



Client: Stratus Redtail Ranch

Project Number: DE0302

Site Name: Stratus Redtail Ranch Site Location: Erie, CO

Photograph ID: 11

Date: 12/18/2017

Direction: N/A

LLC

Comments: Same as above



Photograph ID: 12

Date: 12/19/2017

Direction: N/A

Comments: Drum RTR-153 from

Phase 2A (DFR-12)



Client: Stratus Redtail Ranch

LLC

Project Number: DE0302

Site Name: Stratus Redtail Ranch Site Location: Erie, CO

Photograph ID: 13

Date: 12/20/2017

Direction: N/A

Comments: Plastic found during excavation of Phase 2B (DFR-13)



Photograph ID: 14

Date: 12/20/2017

Direction: N/A

Comments: Plastic found in same trash pile as above in Phase 2B.



Client: Stratus Redtail Ranch

LLC

Project Number: DE0302

Site Name: Stratus Redtail Ranch Site Location: Erie, CO

Photograph ID: 15

Date: 12/20/2017

Direction: N/A

Comments: Label on Drum from

Phase 2B - RTR-104 (DFR-13)



Photograph ID: 16

Date: 12/21/2017

Direction: N/A

Comments: Freon TF Solvent Drum from Phase 1. This is identified on a drum in the drum

staging area.



Client: Stratus Redtail Ranch

LLC

Project Number: DE0302

Site Name: Stratus Redtail Ranch Site Location: Erie, CO

Photograph ID: 17

Date: 12/22/2017

Direction: N/A

Comments: Magnetic Tape from Phase 3 (Test Pit 9) (DFR-15)



Photograph ID: 18

Date: 1/4/2018

Direction: N/A

Comments: Broken Magnetic Tape container from Phase 2B

(DFR-17)



Client: Stratus Redtail Ranch

LLC

Project Number: DE0302

Site Name: Stratus Redtail Ranch Site Location: Erie, CO

Photograph ID: 19

Date: 1/5/2018

Direction: N/A

Comments: Freon TF Solvent label found on drum in Phase 1.

(DFR-18) RTR-106



Photograph ID: 20

Date: 1/5/2018

Direction: N/A

Comments: Same as above.



GEOSYNTEC CONSULTANTS Photographic Record Client: Stratus Redtail Ranch Project Number: DE0302 LLC Site Name: Stratus Redtail Ranch Site Location: Erie, CO

Photograph ID: 21

Date: 1/8/2018 Direction: N/A

Comments: Papers found during Excavation in Phase 2B (DFR-20)



Photograph ID: 22

Date: 1/8/2018

Direction: N/A

Comments: Print on papers

(same as above)



Client: Stratus Redtail Ranch

LLC

Project Number: DE0302

Site Name: Stratus Redtail Ranch Site Location: Erie, CO

Photograph ID: 23

Date: 1/8/2018

Direction: N/A

Comments: Lettering found on Drum Excavated in Phase 2B -

RTR-116 (DFR-20)




Photograph ID: 24

Date: 1/09/2018

Direction: N/A

Comments: Possibly an IBM packing slip encountered in Phase 2B excavations. Label likely read, "IBM 867639" but dissolved

quickly. (DFR-21)



Client: Stratus Redtail Ranch

LLC

Project Number: DE0302

Site Name: Stratus Redtail Ranch Site Location: Erie, CO

Photograph ID: 25

Date: 1/9/2018

Direction: N/A

Comments: Drum RTR-120 Excavated from Phase 2B (DFR-

21)



Photograph ID: 26

Date: 1/9/2018

Direction: N/A

Comments: Label same as above.



GEOSYNTEC CONSULTANTS Photographic Record Client: Stratus Redtail Ranch Project Number: DE0302 LLC Site Name: Stratus Redtail Ranch Site Location: Erie, CO Photograph ID: 27 Date: 1/9/2018 Direction: N/A Comments: Cardboard Excavated from Phase 2B. (DFR-21) Photograph ID: 28 Date: 1/9/2018 Direction: N/A Comments: Same as above

Client: Stratus Redtail Ranch

LLC

Project Number: DE0302

Site Name: Stratus Redtail Ranch Site Location: Erie, CO

Photograph ID: 29

Date: 1/9/2018

Direction: N/A

Comments: Cardboard

Excavated from Phase 2B. (DFR-

21)



Photograph ID: 30

Date: 1/13/2018

Direction: N/A

Comments: Label on cardboard found during excavation in Phase

2B (DFR-25)



Client: Stratus Redtail Ranch

LLC

Project Number: DE0302

Site Name: Stratus Redtail Ranch Site Location: Erie, CO

Photograph ID: 31

Date: 1/13/2018

Direction: N/A

Comments: Print on cardboard found during excavation in Phase

2B



Photograph ID: 32

Date: 1/13/2018

Direction: N/A

Comments: Plastic stamped IBM found during excavation in Phase



Client: Stratus Redtail Ranch

LLC

Project Number: DE0302

Site Name: Stratus Redtail Ranch Site Location: Erie, CO

Photograph ID: 33

Date: 1/13/2018

Direction: N/A

Comments: Broken Magnetic Tape container found during excavation in Phase 2B. (DFR-25)



Photograph ID: 34

Date: 1/14/2018

Direction: N/A

Comments: Cardboard box found during excavation in Phase 2B. The box reads, "IBM Systems Manufacturing Division." (DFR-



Client: Stratus Redtail Ranch

LLC

Project Number: DE0302

Site Name: Stratus Redtail Ranch Site Location: Erie, CO

Photograph ID: 35

Date: 1/18/2018

Direction: N/A

Comments: Broken Magnetic Tape container found during excavation in Phase 2B (DFR-29)



Photograph ID: 36

Date: 1/19/2018

Direction: N/A

Comments: Label on drum RTR-946 found in Phase 2B. Label likely read, "Condor Chemical Company, Pennsylvania 15205, Organic Isocyanite, C-021, Condor CB75" (DFR-30)



Client: Stratus Redtail Ranch

LLC

Project Number: DE0302

Site Name: Stratus Redtail Ranch Site Location: Erie, CO

Photograph ID: 37

Date: 1/20/2018

Direction: N/A

Comments: Drum Excavated from Phase 2B - RTR-840. Drum label read, "Texas Refinery Company" (DFR-31).



Photograph ID: 38

Date: 1/20/2018

Direction: N/A

Comments: Same as above



Client: Stratus Redtail Ranch

LLC

Project Number: DE0302

Site Name: Stratus Redtail Ranch Site Location: Erie, CO

Photograph ID: 39

Date: 1/20/2018

Direction: N/A

Comments: Same as above



Photograph ID: 40

Date: 1/20/2018

Direction: N/A

Comments: Two Magnetic Tape Reels found in Test Pit #14 12018

